TWO-DIMENSIONAL X-RAY DIFFRACTION

BOB BAOPING HE

Second Edition

WILEY

CONTENTS

Preface xiii

1. Introduction 1

1.1 X-Ray Technology, a Brief History, 1
1.2 Geometry of Crystals, 2
1.2.1 Crystal Lattice and Symmetry, 2
1.2.2 Lattice Directions and Planes, 6
1.2.3 Atomic Arrangement in Crystal Structures, 7
1.2.4 Imperfections in Crystal Structure, 10
1.3 Principles of X-Ray Diffraction, 11
1.3.1 Bragg's Law, 12
1.3.2 Diffraction Patterns, 13
1.4 Reciprocal Space and Diffraction, 13
1.4.1 Reciprocal Lattice, 14
1.4.2 The Ewald Sphere, 16
1.4.3 Diffraction Cone and Diffraction Vector Cone, 18
1.5 Two-Dimensional X-Ray Diffraction, 19
1.5.1 Diffraction Pattern Measured by Area Detector, 19
1.5.2 Materials Characterization with 2D Diffraction Pattern, 21
1.5.3 Two-Dimensional X-Ray Diffraction System and Major Components, 23
1.5.4 Summary, 24
References, 26

2. Geometry and Fundamentals 29

2.1 Introduction, 29
2.1.1 Comparison Between XRD^2 and Conventional XRD, 30
2.2 Diffraction Space and Laboratory Coordinates, 31

2.2.1 Diffraction Cones in Laboratory Coordinates, 31
2.2.2 Diffraction Vector Cones in Laboratory Coordinates, 34
2.3 Detector Space and Detector Geometry, 35
2.3.1 Ideal Detector for Diffraction Pattern in 3D Space, 35
2.3.2 Diffraction Cones and Conic Sections with Flat 2D Detectors, 36
2.3.3 Detector Position in the Laboratory System, 36
2.3.4 Pixel Position in Diffraction Space – Flat Detector, 38
2.3.5 Pixel Position in Diffraction Space – Flat Detector Out of Diffractometer Plane, 40
2.3.6 Pixel Position in Diffraction Space – Cylindrical Detector, 43
2.4 Sample Space and Goniometer Geometry, 46
2.4.1 Sample Rotations and Translations in Eulerian Geometry, 46
2.4.2 Variation of Goniometer Geometry, 48
2.5 Transformation from Diffraction Space to Sample Space, 50
2.6 Reciprocal Space, 52
2.7 Summary, 53
References, 55

3. X-Ray Source and Optics 57

3.1 X-Ray Generation and Characteristics, 57
3.1.1 X-Ray Spectrum and Characteristic Lines, 57
3.1.2 Focal Spot and Takeoff Angle, 58
3.1.3 Focal Spot Brightness and Profile, 59
3.1.4 Absorption and Fluorescence, 61
3.1.5 Synchrotron Radiation, 62
3.2 X-Ray Optics, 63
3.2.1 Liouville's Theorem and Fundamentals, 63
3.2.2 X-Ray Optics in Conventional Diffractometer, 65
3.2.3 X-Ray Optics in a Two-Dimensional Diffractometer, 68
3.2.4 The β-Filter, 71
3.2.5 Crystal Monochromator, 73
3.2.6 Multilayer Mirrors, 75
3.2.7 Pinhole Collimator, 80
3.2.8 Capillary Optics, 82
References, 85

4. X-Ray Detectors 87

4.1 History of X-Ray Detection Technology, 87
4.2 Point Detectors in Conventional Diffractometers, 89
4.2.1 Proportional Counters, 90
4.2.2 Scintillation Counters, 91
4.2.3 Solid State Detectors, 91
4.3 Characteristics of Point Detectors, 92
4.3.1 Counting Statistics, 92
4.3.2 Detective Quantum Efficiency and Energy Range, 94
4.3.3 Detector Linearity and Maximum Count Rate, 95
4.3.4 Energy Resolution, 97

4.3.5 Detection Limit and Dynamic Range, 99
4.4 Line Detectors, 100
4.4.1 Geometry of Line Detectors, 100
4.4.2 Types of Line Detectors, 103
4.4.3 Characteristics of Line Detectors, 104
4.5 Characteristics of Area Detectors, 107
4.5.1 Active Area and Angular Coverage, 107
4.5.2 Weight and Dimension, 111
4.5.3 Angular Coverage of Pixels, 112
4.5.4 Spatial Resolution of Area Detectors, 114
4.5.5 Pixel Number and Angular Resolution, 116
4.5.6 Angular Resolution of a 2D Diffractometer, 117
4.6 Types of Area Detectors, 119
4.6.1 Multiwire Proportional Counter, 119
4.6.2 Image Plate, 121
4.6.3 CCD Detector, 122
4.6.4 CMOS Detector, 125
4.6.5 Pixel Array Detector, 126
4.6.6 CPAD Detector, 129
4.6.7 Microgap Detector, 130
4.6.8 Comparison of Area Detectors, 135
References, 137

5. Goniometer and Sample Stages 141

5.1 Goniometer and Sample Position, 141
5.1.1 Introduction, 141
5.1.2 Two-Circle Base Goniometer, 141
5.1.3 Sample Stages, 142
5.1.4 Sequence of the Goniometer Axes, 144
5.2 Goniometer Accuracy, 145
5.2.1 Sphere of Confusion, 145
5.2.2 Angular Accuracy and Precision, 148
5.3 Sample Alignment and Visualization Systems, 149
5.4 Environment Stages, 151
5.4.1 Domed High Temperature Stage, 151
5.4.2 Temperature Stage Calibration, 153
References, 155

6. Data Treatment 157

6.1 Introduction, 157
6.2 Non-Uniform Response Correction, 157
6.2.1 Calibration Source, 158
6.2.2 Non-Uniform Response Correction Algorithms, 159
6.3 Spatial Correction, 161
6.3.1 Fiducial Plate and Detector Plane, 162
6.3.2 Spatial Correction Algorithms, 163
6.4 Detector Position Accuracy and Calibration, 166

6.4.1 Detector Position Tolerance, 168
6.4.2 Detector Position Calibration, 169
6.4.3 Detector Roll Calibration with Diffraction Rings, 171
6.4.4 Intersection Between Diffraction Cones, 171
6.5 Frame Integration, 177
6.5.1 Definition of Frame Integration, 177
6.5.2 Algorithm of Frame Integration – Flat Image, 180
6.5.3 Algorithm of Frame Integration – Cylindrical Image, 185
6.6 Multiple Frame Merge, 186
6.6.1 Merging Multiple Frames, 186
6.6.2 Cylinder Projection of Flat 2D Frames, 187
6.6.3 Merging of the Overlapping Region, 191
6.7 Scanning 2D Pattern, 194
6.8 Lorentz, Polarization, and Absorption Corrections, 197
6.8.1 Lorentz, 197
6.8.2 Polarization, 197
6.8.3 Air Scatter and Be-Window Absorption, 201
6.8.4 Sample Absorption, 203
6.8.5 Combined Intensity Correction, 207
References, 209

7. Phase Identification 211

7.1 Introduction, 211
7.2 Relative Intensity, 212
7.2.1 Multiplicity Factor, 213
7.2.2 Electron and Atomic Scattering, 214
7.2.3 Structure Factor, 215
7.2.4 Attenuation Factors, 216
7.3 Geometry and Resolution, 216
7.3.1 Detector Distance and Resolution, 217
7.3.2 Defocusing Effect, 218
7.3.3 Transmission Mode Diffraction, 220
7.4 Sampling Statistics, 221
7.4.1 Effective Sampling Volume, 222
7.4.2 Angular Window, 223
7.4.3 Virtual Oscillation, 224
7.4.4 Sample Oscillation, 225
7.5 Preferred Orientation Effect, 227
7.5.1 Relative Intensity with Texture, 227
7.5.2 Intensity Correction on Fiber Texture, 229
References, 233

8. Texture Analysis 235

8.1 Introduction, 235
8.2 Pole Density and Pole-Figure, 236
8.3 Fundamental Equations, 238
8.3.1 Pole-figure Angles, 238

8.3.2 Pole Density, 240
8.4 Data Collection Strategy, 242
8.4.1 Single φ Scan, 242
8.4.2 Multiple ϕ Scans, 243
8.4.3 Combination of φ and ω Scans, 246
8.4.4 Goniometer ϕ Rotation Direction, 247
8.4.5 Transmission Mode, 248
8.4.6 Comparison with Point Detector, 250
8.5 Texture Data Process, 251
8.5.1 2θ Integration, 251
8.5.2 Absorption Correction, 255
8.5.3 Pole-Figure Interpolation, 255
8.5.4 Pole-Figure Symmetry, 256
8.5.5 Pole-Figure Normalization, 256
8.6 Orientation Distribution Function, 256
8.6.1 Eulerian Angles and Space, 256
8.6.2 ODF Calculation, 258
8.6.3 Calculated Pole-Figures from ODF, 259
8.7 Fiber Texture, 260
8.7.1 Pole-Figures of Fiber Texture, 262
8.7.2 ODF of Fiber Texture, 262
8.8 Polymer Texture, 264
8.8.1 Data Collection Strategy for Polymers, 264
8.8.2 Pole-Figure from Polymer Film, 265
8.9 Other Advantages of XRD^2 for Texture, 268
8.9.1 Orientation Relationship, 268
8.9.2 Direct Observation of Texture, 268
References, 269

9. Stress Measurement 271

9.1 Introduction, 271
9.1.1 Stress, 272
9.1.2 Strain, 276
9.1.3 Elasticity and Hooke's Law, 277
9.1.4 X-Ray Elasticity Constants and Anisotropy Factor, 278
9.1.5 Residual Stresses, 279
9.2 Principle of X-ray Stress Analysis, 280
9.2.1 Strain and Bragg's Law, 280
9.2.2 Strain Measurement, 282
9.2.3 Stress Measurement, 283
9.2.4 Stress Measurement Without d_o, 286
9.2.5 ψ-Tilt and Goniometer, 288
9.2.6 $\sin^2\psi$ Method with Area Detector, 291
9.3 Theory of Stress Analysis with XRD^2, 292
9.3.1 2D Fundamental Equation for Stress Measurement, 292
9.3.2 Relationship Between Conventional Theory and 2D Theory, 295
9.3.3 2D Equations for Various Stress States, 298
9.3.4 True Stress-Free Lattice d-Spacing, 300

9.3.5 Diffraction Cone Distortion Simulation, 302
9.3.6 Goniometer ϕ Rotation Direction, 306
9.4 Process of Stress Measurement with XRD^2, 307
9.4.1 Instrument Requirements and Configurations, 308
9.4.2 Data Collection Strategy, 309
9.4.3 Data Integration and Peak Evaluation, 313
9.4.4 Stress Calculation, 316
9.4.5 Effect of Texture and Large Grain, 318
9.4.6 Intensity Weighted Least Squares Regression, 318
9.4.7 Stress-Free Sample and Standard Sample, 320
9.4.8 Dynamic Sample Height Alignment, 321
9.4.9 Correction with Stress-Free Sample, 322
9.4.10 Correction with Stress Standard, 324
9.5 Experimental Examples, 325
9.5.1 Comparison Between 2D Method and Conventional Method, 325
9.5.2 Sample Oscillation and Virtual Oscillation, 327
9.5.3 Stress Mapping on Weldment, 329
9.5.4 Residual Stresses in Thin Films, 332
9.5.5 Residual Stress Measurement with Multiple {*hkl*} Rings, 335
9.5.6 Single Tilt Method, 340
9.5.7 Gage Repeatability and Reproducibility Study, 347
A9.1 Calculation of Principal Stresses from the General Stress Tensor, 349
A9.1.1 Calculate Principal Stresses, 349
A9.1.2 Calculate the direction cosines for principal stresses (Eigenvectors), 350
A9.2 Parameters for Stress Measurement, 351
References, 353

10. Small Angle X-ray Scattering 357

10.1 Introduction, 357
10.1.1 Principle of Small Angle Scattering, 357
10.1.2 General Equation and Parameters in SAXS, 358
10.1.3 X-Ray Source and Optics for SAXS, 359
10.2 2D SAXS Systems, 361
10.2.1 SAXS Attachments, 361
10.2.2 Dedicated SAXS System, 364
10.2.3 Detector Correction and System Calibration, 365
10.2.4 Data Collection and Integration, 366
10.3 Applications Examples, 367
10.3.1 Particles in Solutions, 367
10.3.2 Scanning SAXS and Transmission Measurement, 367
10.4 Some Innovations in 2D SAXS, 370
10.4.1 Simultaneous Measurements of Transmission and SAXS, 370
10.4.2 Vertical SAXS System, 372
References, 374

11. Combinatorial Screening 379

11.1 Introduction, 379
11.1.1 Combinatorial Chemistry, 379
11.1.2 High Throughput Screening, 379
11.2 XRD^2 Systems for High Throughput Screening, 380
11.2.1 Screening in Reflection Geometry, 380
11.2.2 Retractable Knife-Edge, 383
11.2.3 Screening in Transmission Geometry, 386
11.3 Combined Screening with XRD^2 and Raman, 390
References, 393

12. Miscellaneous Applications 395

12.1 Percent Crystallinity, 395
12.1.1 Introduction, 395
12.1.2 Comparison of Conventional XRD and XRD^2, 397
12.1.3 Scatter Correction, 397
12.1.4 Internal and External Methods, 398
12.1.5 Full Method, 400
12.2 Crystal Size, 402
12.2.1 Introduction, 402
12.2.2 Line Broadening for Crystallite Size, 402
12.2.3 Crystallite Size Using γ-Profile Analysis, 404
12.3 Retained Austenite, 412
12.4 Crystal Orientation, 414
12.4.1 Orientation with Respect to Sample, 414
12.4.2 Angle Between Two Crystal Planes, 416
12.4.3 Miscut Angle of Single Crystal Wafer, 416
12.5 Thin Film Analysis, 418
12.5.1 Grazing Incidence X-Ray Diffraction, 418
12.5.2 Reflectometry with 2D Detector, 423
12.5.3 Reciprocal Space Mapping, 424
References, 429

13. Innovation and Future Development 433

13.1 Introduction, 433
13.2 Scanning Line Detector for XRD^2, 434
13.2.1 Working Principle, 434
13.2.2 Advantages of Scanning Line Detector, 436
13.3 Three-Dimensional Detector, 438
13.3.1 Third Dimension of a Detector, 438
13.3.2 Geometry of Three-Dimensional Detector, 438
13.3.3 Three-Dimensional Detector and Reciprocal Space, 440
13.4 Pixel Direct Diffraction Analysis, 441

13.4.1 Concept, 441
13.4.2 Pixel Diffraction Vector and Pixel Count, 442
13.4.3 PDD Analysis in Phase-ID, Texture, and Stress, 442
13.5 High Resolution Two-Dimensional X-Ray Diffractometer, 444
13.5.1 Background, 444
13.5.2 HRXRD^2 in Reciprocal Space, 445
13.5.3 New Configuration for HRXRD^2, 447
References, 451

Appendix A. Values of Commonly Used Parameters 453

Appendix B. Symbols 459

Index 465